

TRUCK AND TOOL CLEANER

DESCRIPTION & USE

New Con Truck & Tool is a buffered detergent-based solution designed for cleaning concrete and mortar buildup from construction trucks and tools. No scrubbing is necessary.

ADVANTAGES

- * Not regulated by the D.O.T.
- * Low Odor
- * Non-fuming
- * Improves productivity
- * No V.O.C.'s
- * Can be used with a low pressure rinse
- * Safe for most sensitive colors & substrates

LIMITATIONS

- * Product is very mild but may be corrosive to certain woods, metals, and plants. Covering may be required. Always test.
- * Avoid polished metals as the coating will be affected by the chemical.
- * Do not allow product to dry to any surface.

TECHNICAL DATA

Appearance & Odor: Light colored liquid, mild odor.
Physical State: Liquid
Vapor Pressure (mmHg): As water
Vapor Density (air=1): As water
Boiling Point: 212° F
Freezing/Melting Point: N/A
Specific Gravity (water =1): 1.11
Evaporation Rate: N/A
Solubility in Water: Complete

PREPARATION

Protect adjacent and surrounding surfaces not intended to be cleaned from exposure to the cleaning solution. Avoid direct contact with foliage. Cover landscaping using plastic or wet the foliage with water before and after the cleaning process.

SURFACE & AIR TEMPERATURES

Excessively high or low temperatures will produce poor results and possible harm. Best cleaning results are obtained

when air and surface temperatures are 40° Fahrenheit or above. Do not clean when temperatures are below freezing or will be overnight. If air temperatures exceed 90° Fahrenheit, flash cool the surface with water before applying product. Do not allow products to dry on the surface. Always rinse thoroughly while still wet.

PRE-TESTING

Always test prior to beginning full-scale cleaning operations. Testing should confirm cleaning effectiveness on each type of surface and stain designated to be cleaned. Test also to determine the desired surface contact time and evaluate new potential for adverse reactions with adjacent materials. Allow test area to dry thoroughly before evaluating final appearance and results.

SUITABLE SUBSTRATES

Glass, painted metal, painted fiberglass, and painted plastic.

DILUTION

- 4:1 is the standard dilution on most surfaces

Note: Dilutions will vary based on application and surface to be cleaned

COVERAGE RATES

Coverage rates will vary depending on the surface porosity, texture and severity of the concrete and mortar buildup.

PRE- APPLICATION INFORMATION

Before applying, read "Protect" in the Preparation section and "Precautionary Measures" under Safety Information. Heavy clumps should be removed while chemical soaks on the surface. Use a wood or plastic scraper to remove chunks.

APPLICATION INSTRUCTIONS

Pre-wet the surface with water. Apply New Con Truck & Tool to the truck or tool at a 4:1 rate using the EC Jet attachment. The EC Jet automatically dilutes the product (don't pre-dilute when using EC Jet). Allow New Con Truck & Tool to dwell for 7-10 minutes. Reapply New Con Truck & Tool without rinsing between applications when an extended dwell time is determined.

TRUCK AND TOOL CLEANER

Last, rinse the substrate using appropriate pressure for the situation. 40 degree tip is recommended for final rinse.

Caution: *Do not allow the product to dry on a surface.*

PROTECTION

Most truck or tool materials are not affected by New Con Truck & Tool. Follow proper job site conduct and safety precautions. Chances of causing harm when using accepted standard practices is minimal. Polished metals, some imported stainless steel hardware and some brass coated parts need to be covered and avoided.

SAFETY INFORMATION

Precautionary Measures: Always wear goggles and rubber gloves when handling this product. Keep off of skin and clothing. If material comes in contact with clothing, wash before re-use. Do not dilute New Con Truck & Tool with any other product except water. Do not use for any other applications other than specified. Do not remove label. Avoid polished metals as the coating can be affected. Read Safety Data Sheet for additional safety and health hazard information prior to use. Do not get in eyes, on skin or clothing. Keep container closed when not in use. Use with adequate ventilation. Applicators should wear a rain suit (plastic, rubber or PVC), boots, gloves, face shields and/or goggles to avoid splash to bare skin and eyes. NIOSH/MSHA approved respiration for use with acids if adequate ventilation is unavailable. Though the potential for fuming New Con Truck & Tool is minimal, take precautions to avoid exposing building occupants to fumes. Dispose of empty containers according to federal, state, and local requirements. Avoid drifting of material or rinse water onto surrounding surfaces and pedestrians by protecting or diverting such traffic.

SPILL OR LEAK PROCEDURES

Check with the state, local, or federal regulations for waste disposal methods in the area. Wear proper protective equipment while doing cleanup. For large spills, dike and contain for intended use. For small spills, use a chemical absorbent product and place in approved container for disposal.

CONTAINER HANDLING/STORAGE

Store the product in a cool, dry place away from alkali/base. Vent bung cap before opening. Keep container tightly closed when not in use. Wash thoroughly after handling. Empty containers retain residue and vapors and must be handled as if full. Completely rinse drum prior to disposal.

INSTRUCTIONS IN CASE OF CONTACT OR EXPOSURE

Eyes: Flood with water fifteen minutes and seek medical attention. Do not wear contact lenses when using this product.

Skin: Wash off with soap and water. Remove contaminated clothing.

Ingestion: Drink lots of water to dilute. Do not induce vomiting. Seek immediate medical attention.

Inhalation: Remove to fresh air. If breathing is difficult, seek immediate medical attention.

NOTICE

This product has been classified in accordance with the hazard criteria of the CFR.

DISCLAIMER

The information herein is given in good faith, but no warranty, either expressed or implied is made. Final determination of the suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein we cannot be sure or guarantee these are the only hazards which exist.

CUSTOMER SERVICE

Factory personnel are available for assistance at 724-656-1055 and will send you additional information on products as necessary.

